

Klip-Lok / Klip-Tite Dirt Retention Technical Bulletin 1.1

**ROOFING
LIKE NO OTHER**

Talk to **THE SMART ROOF PEOPLE**
www.globalroofs.co.za
marketing@globalroofs.co.za



Technical Bulletin 1:1: Dirt Retention

Photographs of two projects of equal age – both installed for about 4.5 years. It is noticeable that most of the dirt (black and brown marks) that accumulates on the roof is trapped at the bottom of the narrow flutes, and the bottom of the sides of the longitudinal pan stiffening ribs with minimal accumulation at the transverse pan stiffeners. The dirt accumulation thus follows the height of the upstand – 41mm at the narrow flute, 2mm at the longitudinal pan stiffeners and 0.5mm at the transverse pan stiffeners.

Klip-Lok



Klip-Tite



Please visit our website or contact GRS for standard flashing details

Isando	Tel: +27 (0) 11 898 2900	Bloemfontein	Tel: +27 (0) 51 432 3724	Exports	Tel: +27 (0) 11 898 2900
Cape Town	Tel: +27 (0) 21 521 1900	Nelspruit	Tel: +27 (0) 13 492 0746/7	Botswana	Tel: +267 (002) 310 5761
Durban	Tel: +27 (0) 31 538 0940	Polokwane	Tel: +27 (0) 15 293 0313	Namibia	Tel: +264 (002) 61 263 890
Port Elizabeth	Tel: +27 (0) 43 731 1826	Rustenburg	Tel: +27 (0) 014 596 6121		
East London	Tel: +27 (0) 43 731 1826	Upington	Tel: +27 (0) 54 332 1657		



@GRSRoofs

e.&o.e